

PCDR

A SPECIALLY FORMULATED CLEANER FOR THE COMBUSTION SIDE OF BOILERS

* GOOD WETTING ACTION

* FREE RINSING

* CAUSTIC FREE

* NON-FLAMMABLE

METHOD OF USE

Use neat or diluted with cold water in a 20-50% solution depending on the job. Spray **PCDR** onto the surface and when the product starts to run down stop and wait for the chemical reaction to be completed.

It is preferable to spray more than once instead of one excessive application running to waste. Wait 15-20 minutes after last application then rinse with water spray. A Wet-Vac unit is sometimes helpful.

PRECAUTIONS IN USE:

Do not spray onto hot surfaces.

Do not fire boiler until after water rinse.

PCDR is a powerful detergent cleaner in its undiluted form. Therefore when handling the undiluted products gloves and goggles must be worn. Any splashes on the skin must be washed off with plenty of water.

Paco systems
Broadridge Close
Newton Abbot
Devon TQ12 1YE

Tel: 01626 207064
Fax: 08712 424345
www.paco-systems.co.uk
info@paco-systems.co.uk

*Paints and Coatings
for Industry*